

Headworks Bar Screen - Andritz model 1200x3300x6 – Daphne Utilities

The screen was installed in 2010 and taken out of service in 2019. Screen was operational at that time. Daphne Utilities ordered the recommended parts to repair and update the screen but removed from service instead. Those parts (\$16K value) are included and are still in original packaging. Can email pictures. Contact Goeff Wilkins 251-533-5342 goeff@daphneutilities.com